## K3 Pro Infrared Thermometer

## **Advantages**





Quick Measurement

High Accuracy





Alarm Function

3 Installation Methods





°C/°F Unit Avaliable

Data output



Method of measurement	Sensitivity sensor distance sensor	Operating mode	Surface mode / body mode / Count mode
Temperature Unit	°C/°F	Surface temperature measurement range	1050°C
Accuracy	±0.2 (34~45°C)	Range of Body Mode temperature	3542°C
Measuring distance	5~10 cm	Environment temperature	1040°C
Display	2.8-inch LCD screen	Counting capacity	9999 times
Install Method	Nail hook/bracket fixing	Record temperature data	Support to review 30 sets of data
Power supply	USB /4 AA batteries	Alarm Function	Flash+sound alarm for about 10 seconds
Response time	0.5s	IO signal output	Support(switch signal / pulse signal)
Working band	5um	Body storage	☑ Connect to the computer ☑
Standby time	30s	Volume setting	✓ Voice broadcast ✓
Product Size	170*115*140mm	Backlight switch	☑ Standby ☑
Net weight	303g	Upper alarm limit	☑ Whether to support charging  ☑

Quick measurement

Fever alarm



